

# **Operating Instructions Manual**

# **Tensometric** *HANDY-TENS*

**Electronic Tensionmeter** 

#### **HANDY-TENS**



HANDY-TENS-VK



#### HANDY-TENS-NM



HANDY-TENS-VK2



The electronic Tensometric hand-held unit series HANDY-TENS are used for quick spot check of tensile forces during production and further processing of threads, wires, strands and other flexible material.

They are very easily manageable due to their small size and allow thread tension measuring also at not easily accessible positions in the machine.

The HANDY-TENS can be operated with one hand.

At the push of a button the measured value can be held on the display.

A HANDY-TENS with option -P indicates the peak value by pushing a button.

Included in delivery: **HANDY-TENS** 

> battery 9V 1

operations instruction

case

#### General:

**Tensometric** *HANDY-TENS* is exclusively destined to measure tensile-forces.

After each measurement keep the HANDY-TENS in the little case. If the instrument is not used for a length of time remove battery.

Application: short-time tensile force measuring

### Electrical and Electronic Equipment Act - ElektroG

The tensile force-display device belongs, according to Annex I to ElektroG dated March 16, 2005 Category 9 Monitoring and control equipment and is a B2B product. The exception rule under article 10 para. (2) is claimed. Subsequently the user is obliged to dispose the device properly after the end of its useful life for the purpose of ElektroG. Based on this rule are all devices, which were placed on the market after August 13, 2005. Such devices have a serial number that is greater than 250800.

## **CE Conformity**

The display unit series *HANDY-TENS* meets the standards:

EN 50081-1

Tel.

EN 61000-6-2





## 1. Starting up and handling

Operation the Tensometric *HANDY-TENS* VK should be executed to the instructions given below. Exact execution avoids wrong results.

### 1.1. Operating elements

Fig. 1 HANDY-TENS





Fig. 2 HANDY-TENS Option -P



Fig. 3 HANDY-TENS



## 1.2 Labelling's:

HANDY TENS = Tensile force measuring instrument

Range 0-100,0cN

0-200,0cN 0-300 cN

Options:

-VK = Range 0-2000cN -VK2 = Range 0-80N

-NM = Guiding elements 90° moved

-P = Peak value indication

(1) Digital display

(3a/b) Rocker switch ON-OFF-Damping

(4) Button HOLD frozen present value (5) Guiding elements Meas. pin in the middle

(6) Threading slide switch

(7) Potentiometer CAL for calibration

(8) Battery control BATT in the display

(9) Fixing screws for battery box (10) max. tensile forces (nominal load)

(13) Knop ZERO Zero point adjusting

Option: -P Peak value indication

(12) Button PEAK Peak value indication

(1) Digital display

(2) Button LIGHT for display (3a/b) Rocker switch ON-OFF-Damping

(4) Button HOLD frozen present value

(5) Guiding elements Meas. pin in the middle

(6) Threading slide switch

(7) Potentiometer CAL for calibration

(8) Battery control BATT in the display

(9) Fixing screws for battery box(10) max. tensile forces (nominal load)

(13) Knop ZERO Zero point adjusting



1	.3	Control	elements:
---	----	---------	-----------

(1)	Digital - display		Indication the measured values. Value is revived 3 times/sec.
(2)	Light	Display light	the display lighting is switched on by pressing the button.
(3)	DAMP ON	Switch	For switching-on, use the rocker-switch (3) Rocker-switch (3) is equipped with 3 positions
	Position: ON	Middle Under (left):	instrument is switched - off (3b) instrument is switched-on, measuring values appear with an indication frequency of typ. 3/s unfiltered on the digital-display (1)
	DAMP	Upper (right)	(3a) instrument is switched-on, measuring values appear with an indication frequency of typ. 3/s on the digital-display (1). The signals yet are filtered. In case of fluctuating tensions, thereby the indication is more calm. The values are indicated after 5 sec.
(4)	HOLD	Hold the value	Press the push-button HOLD (4): As long as the button is pressed, the present measured value is indicated on the digital display (1)
(5)	Guiding- and measuring elements		During the measurement, these rollers guide the material in a defined angle round the middle roller (the sensor-roller).  Depending on design of the device:  - either ball bearings rollers - or fixed ceramic thread guides
(6)	Threading- slide- switch		When using the thread lever (Fig. 4-5) the guide elements move downwards. During this position the material can easily be captured. For measuring move back the level into basic position.
(7)	CAL	Calibration	see calibration
(8)	LO BATT Battery-control		When the device is switched on, the display shows the battery symbol lights up on the display when the device is switched on, or the display no longer shows a new battery must be inserted.
(9)	Fixing-screw for the battery-box.		After loosen this screw, the lid of the box can be removed.
(10)	Max. value (nom	ninal load) The lab	el shows the max. value (the nominal load) for the instrument.
(12)	PEAK	Push button	As long as the push-button "PEAK" (12) is pressed, peak values of the measurement will be indicated on the display (1).
(13)	ZERO	Adjusting zero	Before starting the measurement, measuring elements without material, adjust the zero point on the display value 0 with knop (13).



## 2. Inserting the battery

#### Bild 3 open the battery-box



By means of a screwdriver loose the countersunk-screw (9) Now the lid of the battery-box can be removed A small cable, having 2 push-button, is visible

Connect the 9V battery 6 LR 61 to these buttons Push the battery in its housing and screw on the lid

### 3. Measurement

Rocker-switch (3) in position ON (3b), or with fluctuating tension in position shows figures.

DAMP ON (3a). The digital display (1)

2. Without threading the yarn, hold the device that way which is corresponding to the later measuring position 3.


Adjust zero:

Handy-Tens

By turning knop (13) adjust the display (1) to "0"

4. Threading:

Fig. 4




#### **HANDY-TENS**

Move forward the thread lever (see Fig. 4). In this position the material to be measured can easily be captured.

Reduce pressure on thread lever and the guide elements will close.

The thread elements (5) capture the thread.

Fig. 5



## HANDY-TENS-VK

Pull the slide-switch (6) backwards, guide the material between the elements (see fig. 5).

In this position the material to be measured can easily be captured.

Push the slide-switch (6) back in the start-position, the guiding elements are closed. The thread guides (5) catching the threads.

**5. Measuring:** The digital display (1) shows the measured values.

In case, the measured values cannot read out - by continuous pressing the knob HOLD (4),

the presently measured value can be frozen on the display (1).

6. Unthread: HANDY-TENS: Move forward the thread lever (see Fig. 4). In this position the material to be

measured can easily be taken off.

HANDY-TENS-VK: Pull the slide-switch (6) backwards, remove the material

By means of constant pressing HOLD (4) the presently value can be read-out on the display

### 4. Calibration

1.





#### **HANDY-TENS** is calibrated by Tensometric.

Customer must calibrate by using that material which should be measured ensuing



Fig. 6 Calibration:

- Switch (3) in position (3a) ON DAMP
- 2. Adjust the digital display (1) to '000 ' with ZERO
- 3. Hang-up a weight -corresponding to 80% of the HANDY-TENS nominal load

(10), see fig. 6.

- Threading
- 5. The digital display (1) shows a value.
- Now pull the thread with the calibration weight slowly and evenly towards the top, see Fig. 6
- 7. At the same time by means of controller CAL (7) adjust at the digital display (1) that force of the calibration-weight.
- 8. Unthread
- 9. This calibration should be repeated one more time from point 2.

### 5. General:

After each measurement, please keep the *HANDY-TENS* safe in its case.

Please remove the battery in case the instrument is not used for a longer period.

**Application:** Tension measurement on textile or different flexible material.

#### Important:

Please take care on the guiding-elements. An uncontrolled load - p.e. by thumb - on the middle roller - can influence the precision of the instrument or can destroy it.

### 6. Technical Data:

### **HANDY-TENS and HANDY-TENS-NM**

Nominal load: 100,0 cN, or 200,0 cN, or 300 cN

Solution: Type 100,.0 cN und 200,0 cN 0,1 cN steps
Type 300 cN 1 cN steps

Error in meas.:  $< \pm 3 \% (\pm 2 \text{ digits})$ 

Thread speed: max. 1200 m/min with rotating thread guides

No limit with fix ceramic guides

Weight: 0,3 kg

HANDY-TENS-VK: HANDY-TENS-VK-2

Nominal load: 2000 cN Nominal load: 80,0 N Measuring range: 0 - 1999 cN Measuring range: 0 - 80,0 N

Solution: 1 cN steps Solution: 10 cN = 0,1 N steps Error in meas.:  $<\pm 2\%$  ( $\pm 3$  digits) Error in meas.:  $<\pm 2\%$  ( $\pm 3$  digits)

Material speed: max. 2000 m/min max. 2000 m/min With ceramic guides: max. 6000m/min max. 6000m/min

Overload protection: 5 times the nominal load


Indication: Digital, LCD 3 ½ digits, height 10mm, 3 measurements / s
Service voltage: 9V Current: < 10 mA

Battery: 9V battery Type 6LR61 Operating time: approx. 75 h, by using an alkaline battery


Housing: aluminium - metal, alloy anodized Weight: approx. 0,350 kg




## Dimensions HANDY-TENS with rotating tread guides:




## Dimensions HANDY-TENS with fix ceramic guides:









Dimensions HANDY-TENS-NM with fix ceramic guides:









# Dimensions HANDY-TENS-VK-2:

